

The following Instructional documentation is specific to vcarve settings needed to render gcode for use with the crossfire Pro 24 X 24 CNC. It assumes that you already have an understanding of working with vector images and creating profile toolpaths in vcarve. For tutorials on installing and using vcarve, go to our resource page:


<https://www.cedarvalleymakers.org/plasmacnc>

Using Vcarve with the Plasma CNC:

Vcarve is mainly used for CNC machines with spindles. We have programmed a post processor to get the right gcode for the plasma cnc, but there are settings that are set to defaults or are not applicable and should be ignored.

Job Set-up for Langmuir 24 x 24:

Width and height in job setup should be set not greater than 24 x 24 bed size.



Thickness is not important in job set-up, since cutting material thickness will be determined by gas air, and amperage settings at the plasma torch.

XY Datum position should be set depending on where you want your X0, Y0 in relation to your vector image.


Pictured left will start the vector in the lower left corner as shown on the graphic with the red dot.

ToolPaths for the Plasma CNC:

Vectors are cut by creating a vector tool path. Important settings include:

Cut depth: The depth of cut is determined by the plasma torch settings, but vcarve requires a depth of cut. We use .01 and look to ensure the tool path only makes a single pass.

Tool Database




Select the Plasma tip from the tools database. In the notes you will see recommended tip sizes for different thickness of material. These are the recommended torch setting that will be set-up on the torch itself.

Other settings in the plasma tip tool of note:

Diameter .04 is the kerf cut in steel we found with both the .8 and 1.2mm tips. The kerf may vary depending on material and torch settings, so it can be adjusted(D) as needed.


Pass depth is set at .15. This is arbitrary, but the depth of cut on tool path should be less than pass depth, so that there is only a single pass.



Stepover applies to raster and pocket tool paths, so not applicable for plasma operations.

Spindle speed cannot be zero in vcarve, but not applicable for plasma. The gcode created is ignored by the plasma cnc.

Feed rate of 1.1 inches/sec (equates to 70 in/min) has been a good speed for the tips and materials tested to date.



Select climb for direction



TABS - Tabs might be necessary when nesting parts to prevent them from moving in the z height when cut, potentially jamming the torch

head, or otherwise to keep small parts attached to the sheet. When used, two tabs per part .0625 length should be sufficient and relatively easy to break free and grind or file.

Leads are important with Plasma cnc. We have seen good results with a circular lead of .1 inches. Leads can be reduced for small inside diameters but the holes will not be as clean as a drill, so you will want to plan to drill if you want holes that can be tapped or a more exact specification. After calculating the toolpath, run the simulation to ensure cutting operations are performed in a single pass with appropriate leads and tabs. If everything looks as it should;

Click Save toolpath

Select Langmuir Crossfire (inch) from the post processor list.



Click on your created toolpath and then save the toolpath to a usb drive, which can be accessed using the crossfire application, which interprets the gcode for the plasma cnc.

If it is your first time using the weld room, or the cnc at CVM. Request an orientation by e-mailing info@cedarvalleymakers.org.